IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200302308-3

IN RE APPLICATION OF: U.S. Patent No. 6,912,765

USPTO CONFIRMATION CODE: 1585

APPLICATION NO.: 10/663,349

FILED: Sep. 16, 2003

EXAMINER: Essama Omgba

GROUP ART UNIT: 3726

FOR: EASILY REMOVED HEATSINK CLIP

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/663,349, now Patent Number 6,912,765.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a furthfee is required, please charge the amount to Deposit Account No. 082025.
All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.
The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fe is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In column 5, line 53, in Claim 5, delete "cup" and insert - - clip - -, therefor. (Amendment to claims filed on Feb. 18, 2005, page 3, in Claim 26, line 7)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

August 11, 2010
DATE

Name: Reed J. Hablinski Registration No.: 55,238

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 FORT COLLINS CO 80528

- 2 -

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,912,765

APPLICATION NO. : 10/663,349

ISSUE DATE : Jul. 05, 2005

INVENTOR(S) : Gregory C. Franke, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 5, line 53, in Claim 5, delete "cup" and insert - - clip - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY Intellectual Property Administration P. O. Box 272400 Fort Collins, Colorado 80527-2400

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will very depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.